Dear customer, dear distribution Partner,

Our tools are designed for a very long usability. To avoid possible errors when changing the 3 AG5 button cells here is our additional note:

Please double check the correct installation direction (see manual / pictures / tool grip sticker).

<u>Unfortunately some customer do not used the battery-pack tube again</u> after chancing the batteries.

(It is important to use the isolation sleeve.)





Troubleshooting

If you maybe don't have the plastic tube any more, please us a simple piece of paper (24 mm x 14mm) and create a new roll into the battery metal screw. Now the button cells are isolated again.

If the insulating sleeve needs to be replaced or has been discarded: A simple piece of paper or thin foil can do the same function!		
24 mm X 14 mm		

The device itself cannot be defective if the usual handling of measuring devices is observed.

-The integrated laser is good for ~ 10,000 hours.
-Components cannot become defective if handled with care.
-Fault sources such as switches or solder joints are not present.
-The laser unit is vibration resistant.

Mit freundlichen Grüßen Best Regards

Vertrieb / Distribution Office

PROFI PRODUCTS

D-67705 Trippstadt, Floersheimer Ring 6 Tel.: +49 6306-70170 FAX: +49 6306-7017-17